

Amendment to the Specification

Please amend the paragraph at page 14, line 17 as follows:

Fig. 4E ~~illustrates~~ illustrates a prior art blade configuration 5000 having pointed blade edges 5001. This configuration contains the drawback of cutting deeply into conductor 752. This results in a weakening of magnet wire 750. Fig. 4G shows conductor 752 after it has been connected to a prior art blade configuration. Conductor 752 is deeply notched and is substantially weakened structurally.